

Work Order ID 72960

Wednesday, September 21, 2011 3:59:54 PM



Page 1

Item ID: D2570

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 8/22/2011 Start Qty: 32.00



Cust Item ID:

Required Date: 8/23/2011 Req'd Qty: 32.00



Customer: CU-DAR001

Reference: RMA RA111262 - RETURN

Approvals:

Process Plan: MC

Date: 11-09-21

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan - Accept
Code Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D2570

Rev B

100

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

INSPECT RA 111262
D2570 X 32

NO WORK NEEDED
PARTS ARE GOOD

8/10/12

(x72)
count

110

Identify as per dwg & Stock Location: 17

0.00



Packaging

Memo

0.00

Packaging

ID AND STOCK UNDER NEW BATCH NUMBER

11/9/22 32

Work Order ID 72960

Wednesday, September 21, 2011 3:59:54 PM

Page 2

Item ID: D2570

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 8/22/2011 Start Qty: 32.00



Cust Item ID:

Required Date: 8/23/2011 Req'd Qty: 32.00



Customer: CU-DAR001

Reference: RMA RA111262

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start



QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

u/9/27

MF
11-09-22